



209 Dayton Street, Suite 205  
Edmonds, WA 98020-3581

425 771-4482

425 486-1933 Fax

January 25, 2005

ATCB, Inc.  
67312 Whitter Ave.  
McLean, VA 22101

RE: FCC ID: KBCIX300AC775WL

**The specific test reports are applicable as follows:**

<b>Report file name below:</b>	<b>Applicable to:</b>
Exhibit 06 Test Report 1 Pt 22 24 AC775KBCIX300AC775WLBT.pdf	Radiated Spurious and Harmonics ERP/EIRP IX300 and AC775 Part 22/24
Exhibit 6 Test Report 2_Pt 15 WM168B MOLEX KBCIX300AC555WLBT.pdf	Radiated Spurious and Harmonics IX300 WLAN Part 15.247
Exhibit 6 Referenced IX300 Original Twinhead Report WLAN and BT.pdf	All Conducted data for WLAN Part 15.247
Exhibit 6 Sierra Wireless Pt 22_24 OEM Test Report.pdf	All Conducted data for AC775 Part 22/24
Exhibit 6 Test Report Part 15.107_109_207_209 IX300 with AC775.pdf	AC Conducted/ Radiated Emissions for IX300 with AC775 WLAN Part 15.107 & 15.109