


## **APPENDIX 1: Photographs of test setup**


### **Radiated Emission**

#### **Door handle antenna**

##### **Front**



##### **Rear**



---

**UL Japan, Inc.**

**Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124


## **Radiated Emission**

### **Room antenna**

#### **Front**



#### **Rear**



---

**UL Japan, Inc.**

**Head Office EMC Lab.**


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116


Facsimile : +81 596 24 8124

**Worst Case Position (Module: X-axis / Antenna: X-axis)**

**Module**  
**X-axis**



**Y-axis**




**Z-axis**



**Room antenna**  
**X-axis**



**Y-axis**



**Z-axis**



---

**UL Japan, Inc.**


**Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

**Door handle antenna**  
**X-axis**



**Y-axis**



**Z-axis**



---

**UL Japan, Inc.**

**Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124