

APPENDIX 3: Photographs of test setup

Radiated Emission (Below 1GHz)




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Emission
(Above 1GHz)




Photo 1





Photo 2

Worst Case Position

Above 1GHz: Horizontal: X-axis / Vertical: X-axis
Below 1GHz: Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124