

August 30, 2011

Timco Engineering 849 NW State Road 45 Newberry, Florida 32669

RE: Change in ID Request for Radio Systems:

New Model: 300-1174

New FCC ID: KE3-3001174 New IC: 2721A-3001174

Dear Applications Examiner:

Radio Systems is requesting a change in FCC and IC ID for the above referenced model. This request is for marketing purposes only and no changes have been made to any portion of the originally approved equipment. Following are the details of the change request:

- 1. **The original equipment identification was**: Grantee: Tracker OY Model: T60, FCC ID: YBW-T60, IC: 89332A-T60.
- 2. The date of the original grant of authorization was: May 12, 2010
- 3. **Equipment differences from original grant:** Grantee, model, and FCC and IC ID numbers only have changed. There are no changes from the original equipment.
- 4. **Original Test Result Changes:** There are no changes from the original test results.
- 5. **Photographs:** Detailed external and internal photographs and a label drawing have been uploaded as separate documents.

Sincerely,

Alan Ghasiani

Consulting Engineer - President

Slan Shasian