



Tune Up Procedure

Date: November 22, 2019

Subject: Tune Up Procedure for: FCC ID: KE3-3003591

The RF Transceiver chip (CC1120) for the Model RIG00-16936 is fully synthesized. There is no factory tuning.

The MURS radio testing performed at the fundamental signal of 151.82 MHz was done at the default output power setting of +16 dBm to the RF port of the radio transmitter. The setting is not user adjustable. The antenna radiated field strength was then measured and reported as the maximum ERP level for the radio. This value is recorded in Table 4 of the test report.

Sincerely,

By: *Sandi McEnergy*
(Signature/Title)

Sandi McEnergy - Agent
(Print name)