



M3388A Before change

<p>MODEL M33051A 100-120V~ 1.2-1A 50-60Hz</p>	 NRTL/C <input type="checkbox"/>	<p>FCC ID: C9SDP040M3388A1</p>
<p>DATE <input type="checkbox"/></p>		<p>THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.</p>
<p>FUJITSU ISOTEC LIMITED</p>		<p>MADE IN JAPAN</p>

M3388A After change

<p>MODEL M33051A 100-120V~ 1.2-1A 50-60Hz</p>	 NRTL/C 172998 <input type="checkbox"/>	<p>FCC ID: KHZ005M3388A</p>
<p>DATE <input type="checkbox"/></p>		<p>THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.</p>
<p>FUJITSU ISOTEC LIMITED</p>		<p>MADE IN JAPAN</p>

FCC ID: KHZ005M3388A



FCC label location