



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 20, 2002

RE: Savi Technology

FCC ID: KL7-600SP-V3

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) It is not clear where the FCC label will go on the device. Please explain.
- 2) The data given on page 6 of 9 appears to be the worse case data for the scan, however, none of this data appears on the previous page. Please explain.
- 3) The test report does not present any data for the > 30 MHz for the digital device portion of the test. Please confirm if this testing has been completed (15.109).

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.