




TO TURN DSR LINE INTO RESET LINE,
(NOT AVAILABLE ON WATERPROOF MODEL)
REMOVE C2, D1, & SHORTEN TP3 & TP4

D000000000

IDN L

TP1
TP2
TP3
TP4
TP5
TP6
TP7
TP8



PCS JETPOWER

IDN

TO TURN DSR LINE INTO RESET LINE:
(NOT AVAILABLE ON WATERPROOF MODEL)
REMOVE C2, D1, & R1 ON BACK AND
SHORT TP8 TO TP9

