

COLLEGE OF ENGINEERING THE RADIATION LABORATORY DEPARTMENT OF ELECTRICAL ENGINEERING AND COMPUTER SCIENCE

3228 EECS BUILDING 1301 BEAL AVENUE ANN ARBOR, MICHIGAN 48109-2122 734 764-0500 FAX 734 647-2106 http://www.eecs.umich.edu/RADLAB/

Re: Class II Permissive Change/Re-assessment

for Lear NG WCM Receiver

PN(s): 05E01G01

FCC ID: KOBDR06WB IC: 3521A-DR06WB

POWER OF ATTORNEY

A letter granting Valdis V. Liepa the Power of Attorney is on file and can be provided when so requested.



COLLEGE OF ENGINEERING THE RADIATION LABORATORY DEPARTMENT OF ELECTRICAL ENGINEERING AND COMPUTER SCIENCE

3228 EECS BUILDING 1301 BEAL AVENUE ANN ARBOR, MICHIGAN 48109-2122 734 764-0500 FAX 734 647-2106 http://www.eecs.umich.edu/RADLAB/

Re: Class II Permissive Change/Re-assessment

for Lear NG WCM Receiver

PN(s): 05E01G01

FCC ID: KOBDR06WB IC: 3521A-DR06WB

REQUEST FOR CONFIDENTIALITY

Pursuant to 47 CRF 0.459, Lear requests that a part of the subject application be held confidential. This comprises Exhibits

- (5) Schematics
- (10) Parts List

Lear has spent substantial effort in developing this product and it is one of the first of its kind in industry. Having the subject information easily available to "competition" would negate the advantage they have achieved by developing this product. Not protecting the details of the design will result in financial hardship.

If there are any questions regarding this request, please contact me at the above address or call 734-483-4211, fax 734-647-2106 or e-mail liepa@umich.edu.

Sincerely, Nald? V. Liga

Valdis V. Liepa Research Scientist University of Michigan

University Of Michigan College Of Engineering

THE RADIATION LABORATORY DEPARTMENT OF ELECTRICAL ENGINEERING AND COMPUTER SCIENCE

3228 EECS BUILDING 1301 BEAL AVENUE ANN ARBOR, MICHIGAN 48109-2122 734 764-0500 FAX 734 647-2106 http://www.eecs.umich.edu/RADLAB/

March 20, 2007

Re: Class II Permissive Change/Re-assessment

for Lear NG WCM Receiver

PN(s): 05E01G01

FCC ID: KOBDR06WB IC: 3521A-DR06WB

CHANGES MADE

The current Receiver was modified by the addition of an active switching (AS) baseband as well as a real time clock (RTC). The active switching baseband made it necessary to declare this change a Class II change.



COLLEGE OF ENGINEERING THE RADIATION LABORATORY DEPARTMENT OF ELECTRICAL ENGINEERING AND COMPUTER SCIENCE

3228 EECS BUILDING 1301 BEAL AVENUE ANN ARBOR, MICHIGAN 48109-2122 734 764-0500 FAX 734 647-2106 http://www.eecs.umich.edu/RADLAB/

March 20, 2007

Re: Class II Permissive Change/Re-assessment

for Lear NG WCM Receiver

PN(s): 05E01G01

FCC ID: KOBDR06WB IC: 3521A-DR06WB

STATEMENT OF MODIFICATIONS

There were no modifications made to the DUT by this test laboratory. (Also see Section 3.1 of the attached Test Report).

Valdis V. Liepa

Research Scientist

Nald? V. Lipa



COLLEGE OF ENGINEERING THE RADIATION LABORATORY DEPARTMENT OF ELECTRICAL ENGINEERING AND COMPUTER SCIENCE

3228 EECS BUILDING 1301 BEAL AVENUE ANN ARBOR, MICHIGAN 48109-2122 734 764-0500 FAX 734 647-2106 http://www.eecs.umich.edu/RADLAB/

Re: Class II Permissive Change/Re-assessment

for Lear NG WCM Receiver

PN(s): 05E01G01

FCC ID: KOBDR06WB IC: 3521A-DR06WB

GENERAL PRODUCT INFORMATION

The device, for which certification is pursued, has been designed by:

Lear Corporation 5200 Auto Club Drive Dearborn, MI 48126

Tom Tang, ttang@lear.com Tel: (313) 593-9934 Fax: (313) 240-3062

It will be manufactured by:

Lear Corporation 5100 West Waters Avenue Tampa, FL 33634

> Tom Tang Tel: (313) 593-9934 Fax: (313) 240-3062

Canadian Contact:

Tom Odell 1908 Colonel Sam Drive Oshawa, ON. L1H 8P7 Tel: (905) 644-7103