



5200 Auto Club Dr.
Dearborn, MI 48126
(313) 593-9000

Date: April 16, 2002

Re: Certification for Lear Corporation, Transmitter Model RLC-X and RLC-C+.

Description of Changes

For the following modules:

Model	FCC ID	Canada ID
RLC-X, RLC-C+	KOBLEAR1XT	3521 102 1718

The following changes were made:

- Moved capacitor C3.
- Antenna layout changed.
- Changed vendors for the SAW resonator.
- Changed vendors for some of the capacitors.