


3-7. Circuit Diagram




Note


1. L2 and L3 are copper, not parts.

2. Not mounted: L2, L3, C4, C5, C11 ~ C14, C16

3-9. PWB pattern
(1) A-side



(2) B-side



3-10. Appearance

