

**Continental Automotive GmbH,**  
Siemensstraße 12,  
93055 Regensburg, Germany

**FCC ID:** KR5DWMI2017A

**Model:** D-WMI2017A

### **Compliance Statement in User Manual**

To whom it may concern

Our product with the above FCC ID are marketed together with cars, where it`s operation is included in the individual owner`s manual of the cars.

We hereby assure that the following caution statement as per CFR, §15.21 is included in a prominent location of the owner`s manual of the cars:

The title **“CAUTION TO USERS”** or **“FCC WARING”**, **“NOTE”** or relevant title and **“Changes or modifications not expressly approved by the party responsible for compliance could void the user`s authority to operate the equipment.”**

And also

**“A separation distance of at least 10 cm between all persons and the device must be provided at all times. The Device must not be co-located or operating in conjunction with any other antenna or transmitter.”**

In addition, we also assure that the following statement is also included in a prominent location in the manual as per CFR 47, §15.19(a)(3):

**This device complies with Part 15 of the FCC Rules.**

**Operation is subject to the following two conditions:**

- (1) This device may not cause harmful interference, and**
- (2) This device must accept any interference received, including interference that may cause undesired operation.**

If you have any questions, please feel free to contact me at the address shown below.

Yours sincerely,



---

By: Dagmar Kolar  
Title: RF Homologation  
Company: Continental Automotive GmbH  
Telephone: +49 941 790-6699  
e-mail: [Dagmar.Kolar@continental-corporation.com](mailto:Dagmar.Kolar@continental-corporation.com)