
Tel: +886 2 26099301 Fax: +886 2 26099303


B.1 Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie



Side




File Number: C1M1805034

Report Number: EM-F180201




Tel: +886 2 26099301 Fax: +886 2 26099303

Stand



Frequency Above to 1GHz

Lie



File Number: C1M1805034


Report Number: EM-F180201

Tel: +886 2 26099301


 Dingfu, Linkou, Dist.,
 Fax: +886 2 26099303

 City244, Taiwan
 Fax: +886 2 26099303





Stand





Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 RF Conducted Measurement

