


New Taipei City244, Taiwan

Tel: +886 2 26099301 Fax: +886 2 26099303


# **B.1** Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie



Side



File Number: C1M1807228


Report Number: EM-F180329



Audix Technology Corp.
No. 53-11, Dingfu, Linkou, Dist.,
New Taipei City244, Taiwan


Tel: +886 2 26099301 Fax: +886 2 26099303

#### Stand



Frequency Above to 1GHz

Lie




File Number: C1M1807228

Report Number: EM-F180329




Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

### Side



#### Stand





Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan Tel: +886 2 26099301 Fax: +886 2 26099303

## **B.2** RF Conducted Measurement

