



APPENDIX B-Page 1 of 2 Tel: +886 2 26099301 Fax: +886 2 26099303

B.1. Radiated Measurement at Chamber

Frequency Below to 1GHz



Frequency Above to 1GHz



File Number: C1M1806082


Report Number: EM-F180250

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 2 of 2 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2. RF Conducted Measurement



File Number: C1M1806082

Report Number: EM-F180250

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.