


No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan APPENDIX B-Page 1 of 4

Tel: +886 2 26099301 *Fax:* +886 2 26099303

B.1 Radiated Measurement at Chamber

Frequency Below to 1GHz

Lie



File Number: C1M2104110Report Number: EM-F210379This test report may be reproduced in full only. The document may only be updated by Audix Technology
Corp. personnel. Any changes will be noted in the Document History section of the report.




Audix Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan APPENDIX B-Page 2 of 4

Tel: +886 2 26099301 *Fax:* +886 2 26099303



Frequency Above to 1GHz Lie




File Number: C1M2104110Report Number: EM-F210379This test report may be reproduced in full only. The document may only be updated by Audix Technology
Corp. personnel. Any changes will be noted in the Document History section of the report.




Audix Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan APPENDIX B-Page 3 of 4

Tel: +886 2 26099301 *Fax:* +886 2 26099303



Stand



File Number: C1M2104110Report Number: EM-F210379This test report may be reproduced in full only. The document may only be updated by Audix Technology
Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 4 of 4

Tel: +886 2 26099301 *Fax:* +886 2 26099303

Audix Technology Corp. No. 491, Zhongfu Rd., Linkou Dist., New Taipei City244, Taiwan



B.2 RF Conducted Measurement

File Number: C1M2104110

Report Number: EM-F210379

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.