

|                                                                  |                                                                                     |                                                                          |
|------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|
| <b>PHONAK</b><br>communication systems<br><br><b>Development</b> | <b>Technical Note</b><br><br><b>Test Setup Photos</b><br><b>Phonak Roger MyLink</b> | Doc.: TN150414.doc<br>Vers.: <b>V1</b><br>Page: 1 of 2<br>Date: 15.04.14 |
|------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|

## Phonak Roger MyLink Test Setup Photos



Fig 1 Radiated measurements - carrier



Fig 2 Spurious emissions 30 MHz – 1GHz

|                                                                  |                                                                                     |                                                                          |
|------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|
| <b>PHONAK</b><br>communication systems<br><br><b>Development</b> | <b>Technical Note</b><br><br><b>Test Setup Photos</b><br><b>Phonak Roger MyLink</b> | Doc.: TN150414.doc<br>Vers.: <b>V1</b><br>Page: 2 of 2<br>Date: 15.04.14 |
|------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|




Fig 3 Spurious emissions – 1 GHz- 26.5 GHz