


Photo 1. Top of Battery Half and Transceiver, Cover On



Class 1 Division 1 Groups A-D

E112430

INTRINSICALLY SAFE  
SÉCURITÉ INTRINSÈQUE  
Exia



Warning! To prevent ignition of a hazardous atmosphere, batteries must only be changed in an area known to be nonhazardous.

Avertissement! Afin de prévenir, l'inflammation d'atmosphères dangereuses, ne changer les batteries que dans des emplacements désignés non dangereux.

Warning! To prevent ignition of flammable or combustible atmospheres, disconnect power before servicing.

Axonm P/N 2100-0220-01


Battery P/N 2100-0241-01 Rating 3.6V

FCC ID: L2V-STAMP1

IC ID: 3989A-STAMP1

ICES-003/(A/B)

CE R&TTE: TBR41



Contains IC ID: 3989A-STX21

Contains FCC ID: L2V-STX-21



Complies with FCC standards.  
FOR HOME OR OFFICE USE

This device complies with Part 15 of the FCC rules.  
Operation is subject to the following two conditions:

(1) This device may not cause harmful interference,  
and (2) this device must accept any interference  
received, including interference that may cause  
undesired operation.

U.S. Patents: 4,977,577; 5,987,058;  
6,317,029; 6,396,819; 7,099,700; and  
other patents pending