

**SPORTON International Inc.**

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

**FCC TEST REPORT**


**REPORT NO. : F832508**

**5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION**

FRONT VIEW



REAR VIEW



**SPORTON International Inc.**


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

**FCC TEST REPORT**

**REPORT NO. : F832508**

SIDE VIEW



APPLICANT : CIS TECHNOLOGY INC.  
EQUIPMENT : MODEM CARD

FCC ID : L4OWS-5614PS3  
ISSUED DATE : MAR. 30, 1998  
PAGE NUMBER : 16 OF 23

**SPORTON International Inc.**

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

**FCC TEST REPORT**

**REPORT NO. : F832508**

**6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION**

**FRONT VIEW**



**REAR VIEW**

