



CMI, Cover Opened




FCC ID: L5H94117V190B




CMI, Components Removed, Showing Power Amplifier, Transceiver, Power Supply And Power Extractor

FCC ID: L5H94117V190B

CMI Transceiver, Downstream CCA Cover Removed




FCC ID: L5H94117V190B




CMI Transceiver, Downstream CCA, Top

FCC ID: L5H94117V190B

CMI Transceiver, Downstream CCA, Bottom



FCC ID: L5H94117V190B



CMI Transceiver, Downstream Cavity


FCC ID: L5H94117V190B





CMI Transceiver, Upstream CCA Cover Removed

FCC ID: L5H94117V190B




CMI Transceiver, Upstream CCA, Top


FCC ID: L5H94117V190B



CMI Transceiver, Upstream CCA, Bottom



FCC ID: L5H94117V190B




CMI Transceiver, Upstream Cavity

FCC ID: L5H94117V190B

CMI Power Supply




FCC ID: L5H94117V190B



CMI Power Supply, Shield Removed


FCC ID: L5H94117V190B

CMI Power Extractor, Cover Removed




FCC ID: L5H94117V190B

HIC, Top Cover Removed



FCC ID: L5H94117V190B







HIC, Top Cover And Top CCA Shields Removed

FCC ID: L5H94117V190B

HIC, Bottom Cover Removed




FCC ID: L5H94117V190B



HIC, Bottom Cover And Bottom CCA Shields Removed

FCC ID: L5H94117V190B



HIC, Bottom Cover And Bottom CCA Shields Removed, Daughter Card Removed

FCC ID: L5H94117V190B