



CMI, Cover Opened




FCC ID: LSH94117V190C



CMI, Components Removed, Showing Power Amplifier, Transceiver, Power Supply And Power Extractor


FCC ID: L5H94117V190C

CMI Transceiver, Downstream CCA Cover Removed




FCC ID: L5H9417V190C

CMI Transceiver, Downstream CCA, Top



FCC ID: L5H94117V190C




CMI Transceiver, Downstream CCA, Bottom

FCC ID: L5H94117V190C

CMI Transceiver, Downstream Cavity

FCC ID: L5H94117V190C








CMI Transceiver, Upstream CCA Cover Removed


FCC ID: L5H94117V190C



CMI Transceiver, Upstream CCA, Top


FCC ID: L5H94117V190C





CMI Transceiver, Upstream CCA, Bottom

FCC ID: L5H9417V190C



CMI Transceiver, Upstream Cavity


FCC ID: L5H94117V190C

CMI Power Supply




FCC ID: L5H94117V190C





CMI Power Extractor, Cover Removed


FCC ID: L5H94117V190C



HIC, Top Cover Removed


FCC ID: L5H94117V190C






HIC, Top Cover And Top CCA Shields Removed

FCC ID: L5H94117V190C




HIC, Bottom Cover Removed

FCC ID: L5H94117V190C



HIC, Bottom Cover And Bottom CCA Shields Removed

FCC ID: L5H94117V190C



HIC, Bottom Cover And Bottom CCA Shields Removed, Daughter Card Removed

FCC ID: L5H94117V190C