RTS RIM Testing Services	Annex C to Hearing Aid C Report for BlackBerry Wir			Page 1(5)
Author Data	Dates	Report No	FCC ID	
Daoud Attayi	July 13-19, 31, 2006	RTS-0373-0607-14	L6ARBF20CW	

Annex C: Test set up photos

RTS RIM Testing Services	Annex C to Hearing Aid Report for BlackBerry W			Page 2(5)
Author Data	Dates	Report No	FCC ID	
Daoud Attayi	July 13-19, 31, 2006	RTS-0373-0607-14	L6ARBF20CW	

Acoustic output center

Axial T-Coil Center



Voice microphone

Figure 1. BlackBerry Wireless Handheld

RTS RIM Testing Services	Annex C to Hearing Aid Report for BlackBerry W			Page 3(5)
Author Data	Dates	Report No	FCC ID	
Daoud Attayi	July 13-19, 31, 2006	RTS-0373-0607-14	L6ARBF20CW	



 $Figure\ 2-Dipole\ validation\ \ setup$

RTS RIM Testing Services	_	Compatibility RF Emiss Vireless Handheld Mode		Page 4(5)
Author Data	Dates	Report No	FCC ID	
Daoud Attayi	July 13-19, 31, 2006	RTS-0373-0607-14	L6ARBF20CW	




Figure 3 – PMF measurement setup

RTS RIM Testing Services	Annex C to Hearing Aid Report for BlackBerry V			Page 5(5)
Author Data	Dates	Report No	FCC ID	
Daoud Attayi	July 13-19, 31, 2006	RTS-0373-0607-14	L6ARBF20CW	




Figure 4 – HAC RF emissions test setup