RTS	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			Page 1(6)
RIM Testing Services	•			
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20C	W

Annex E: Test Setup Photos

RTS	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			Page 2(6)
RIM Testing Services				
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attavi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20CW	



Figure E1: BlackBerry Wireless Handheld

RTS	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			
RIM Testing Services	•			
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attavi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20CW	




Figure E2: Probe calibration and reference signal measurement setup

RTS	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			Page 4(6)
RIM Testing Services				
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20CW	



Figure E3: Ambient noise measurement setup

RTS	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			Page 5(6)
RIM Testing Services				
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20CW	



RTS	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry Wireless Handheld Model RBF20CW			Page 6(6)
RIM Testing Services				
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attavi	May 14, June 30, July 4, 2006	RTS-0373-0607-15	L6ARBF20CW	




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup