

RTS RIM Testing Services	<small>Document</small> Annex C to Hearing Aid Compatibility RF Emissions Test Report for BlackBerry Wireless Handheld Model RBK41CG		<small>Page</small> 1(5)
<small>Author Data</small> Daoud Attayi	<small>Dates</small> Jan. 25 – Feb. 19, 2007	<small>Report No</small> RTS-0491-0703-04	<small>FCC ID</small> L6ARBK40CG

Annex C: Test set up photos

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for BlackBerry Wireless Handheld Model RBK41CG		Page 2(5)
	Author Data Daoud Attayi	Dates Jan. 25 – Feb. 19, 2007	Report No RTS-0491-0703-04



Figure 1. BlackBerry Wireless Handheld

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for BlackBerry Wireless Handheld Model RBK41CG		Page 3(5)
	Author Data Daoud Attayi	Dates Jan. 25 – Feb. 19, 2007	Report No RTS-0491-0703-04




Figure 2 – Dipole validation setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for BlackBerry Wireless Handheld Model RBK41CG		Page 4(5)
	Author Data Daoud Attayi	Dates Jan. 25 – Feb. 19, 2007	Report No RTS-0491-0703-04




Figure 3 – PMF measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for BlackBerry Wireless Handheld Model RBK41CG		Page 5(5)
	Author Data Daoud Attayi	Dates Jan. 25 – Feb. 19, 2007	Report No RTS-0491-0703-04




Figure 4 – HAC RF emissions test setup