

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBU21CW		Page 1(5)
Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03	FCC ID L6ARBU20CW

Annex C: Test set up photos

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBU21CW		Page 2(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03

Acoustic output center & Axial T-Coil Center



Voice microphone

Figure 1 - BlackBerry® Smartphone

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBU21CW		Page 3(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03




Figure 2 – Dipole validation setup

RTS RIM Testing Services	Document	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBU21CW		Page 4(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03	FCC ID L6ARBU20CW




Figure 3 – PMF measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBU21CW		Page 5(5)
	Author Data Daoud Attayi	Dates of Test 08-24 Dec, 07 and 07 Jan, 08	Report No RTS-0943-0801-03





Figure 4 – HAC RF emissions test setup