

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 1(6)
Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30	FCC ID L6ARBW70CW

Annex C: Test set up photos

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 2(6)
	Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30
		FCC ID L6ARBW70CW	



Figure 1. BlackBerry Smartphone

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 3(6)
	Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30





Figure 2 – RF Ambient Noise measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 4(6)
	Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30






Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 5(6)
	Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30



RTS RIM Testing Services	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RBW71CW		Page 6(6)
	Author Data Daoud Attayi	Dates of Test Aug 26, Sep 26-27, 2008	Report No RTS-1191-0809-30

Figure 4 – HAC RF emissions test setup