
	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDC71UW		Page 1(5)
Author Data Andrew Becker	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18A	FCC ID L6ARDD70UW L6ARDC70UW

Annex C: Test set up photos


	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDC71UW		Page 2(5)
	Author Data Andrew Becker	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18A



Audio Output (0, 0)

Telecoil (-5mm, 13mm)



Figure C1. BlackBerry Smartphone

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDC71UW		Page 3(5)
	Author Data Andrew Becker	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18A






	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDC71UW		Page 4(5)
	Author Data Andrew Becker	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18A

Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup




	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDD71UW/RDC71UW		Page 5(5)
Author Data Andrew Becker	Dates of Test Feb 28, Mar. 22-23, Apr. 05, May 13-16, June 20-21, July 11, 2011	Report No RTS-2579-1107-18A	FCC ID L6ARDD70UW L6ARDC70UW

Figure C3 – HAC RF emissions test setup