

	Document		Page
	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW		1(5)
Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	May 12-27, 2011	RTS-2579-1107-19	L6ARDD70UW

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW		Page 2(5)
Author Data Daoud Attayi	Dates of Test May 12-27, 2011	Report No RTS-2579-1107-19	FCC ID L6ARDD70UW

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW		Page 3(5)
	Author Data Daoud Attayi	Dates of Test May 12-27, 2011	Report No RTS-2579-1107-19

Audio Output (0, 0)

Telecoil (-5mm, 13mm)



Figure E1. BlackBerry Smartphone





Figure E2: Ambient noise and system validation measurement setup





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup