Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic		Page 1(4)	
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-10, 2011	RTS-3640-1103-10	L6ARDM70UW	

Annex E: Test set up photos

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW		Page 2(4)	
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-10, 2011	RTS-3640-1103-10	L6ARDM70UW	



Figure E1. BlackBerry Smartphone

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic		Page 3(4)	
Author Data	Dates of Test	Report No	FCC ID	•
Daoud Attayi	Mar. 09-10, 2011	RTS-3640-1103-10	L6ARDM70UW	7





Figure E2: Ambient noise and system validation measurement setup

Testing Services™


Annex E to Hearing Aid Compatibility Audio Band Magnetic

(ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW

4(4)

Page

Author Data **Daoud Attayi** Dates of Test Mar. 09-10, 2011 Report No RTS-3640-1103-10 FCC ID L6ARDM70UW






Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup