
	Document		Page
	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDH71CW/RDP71UW		1(5)
Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	Jan. 12-19, 2011 Feb. 28-Mar. 01, 2011	RTS-2605-1102-02A	L6ARDH70CW L6ARDP70UW

Annex C: Test set up photos

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDH71CW/RDP71UW		Page 2(5)
	Author Data Daoud Attayi	Dates of Test Jan. 12-19, 2011 Feb. 28-Mar. 01, 2011	Report No RTS-2605-1102-02A

Audio Output (0, 0)

Telecoil (-3mm, 10mm)




Figure E1. BlackBerry Smartphone



	Document		Page
	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDH71CW/RDP71UW		3(5)
Author Data Daoud Attayi	Dates of Test Jan. 12-19, 2011 Feb. 28-Mar. 01, 2011	Report No RTS-2605-1102-02A	FCC ID L6ARDH70CW L6ARDP70UW



Figure 2 – Dipole Validation & Probe Modulation Factor measurement setup

	Document		Page
	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDH71CW/RDP71UW		4(5)
Author Data Daoud Attayi	Dates of Test Jan. 12-19, 2011 Feb. 28-Mar. 01, 2011	Report No RTS-2605-1102-02A	FCC ID L6ARDH70CW L6ARDP70UW






Figure 3 – Dipole Validation & Probe Modulation Factor measurement setup

	Document Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RDH71CW/RDP71UW		Page 5(5)
	Author Data Daoud Attayi	Dates of Test Jan. 12-19, 2011 Feb. 28-Mar. 01, 2011	Report No RTS-2605-1102-02A





Figure 4 – HAC RF emissions test setup