Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDV71UW			Page 1(4)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-April 28, 2011	RTS-3933-1105-51C RTS-2580-1106-42	L6ARDU70CW L6ARDV70UW	


Annex E: Test set up photos

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDV71UW			Page 2(4)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-April 28, 2011	RTS-3933-1105-51C	L6ARDU70CW	
		RTS-2580-1106-42	L6ARDV70UW	



Figure E1. BlackBerry Smartphone

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDV71UW			Page 3(4)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-April 28, 2011	RTS-3933-1105-51C RTS-2580-1106-42	L6ARDU70CW L6ARDV70UW	







Figure E2: Ambient noise and system validation measurement setup

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDU71CW/RDV71UW			Page 4(4)
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Mar. 09-April 28, 2011	RTS-3933-1105-51C RTS-2580-1106-42	L6ARDU70CW L6ARDV70UW	






Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup