Testing Services™	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model REA71UW			Page <b>1(4)</b>
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Feb 28, Mar. 22-23, Apr. 05, Aug. 09-31, 2011	RTS-5316-1109-55	L6AREA70UW	

Annex C: Test set up photos

Testing Services™	Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model REA71UW			Page <b>2(4)</b>
Author Data	Dates of Test	Report No	FCC ID	
Daoud Attayi	Feb 28, Mar. 22-23, Apr. 05, Aug. 09-31, 2011	RTS-5316-1109-55	L6AREA70U	W

Audio Output (0, 0)



Figure C1. BlackBerry Smartphone

謝	Testing Services™
---	----------------------

Document

Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model REA71UW

Page

3(4)

Author Data


Daoud Attayi

Feb 28, Mar. 22-23, Apr. 05, Aug. 09-31, 2011

Report No **RTS-5316-1109-55** 

FCC ID

L6AREA70UW






Figure C2 – Dipole Validation & Probe Modulation Factor measurement setup



Document

Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model REA71UW

4(4)

Page

Author Data

**Daoud Attayi** 

Dates of Test

Feb 28, Mar. 22-23, Apr. 05, Aug. 09-31, 2011 Report No

RTS-5316-1109-55

FCC ID

L6AREA70UW






Figure C3 – HAC RF emissions test setup