Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 1(4)
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-2, 2012	RTS-5994-1203-63	L6AREY20CW	

Annex E: Test set up photos



Figure E1. BlackBerry Smartphone

This report shall <u>NOT</u> be reproduced except in full without the written consent of RIM Testing Services Copyright 2005-2012 RIM Testing Services , A division of Research In Motion Limited

Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 3(4)
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-2, 2012	RTS-5994-1203-63	L6AREY20CW	



Figure E2: Ambient noise and system validation measurement setup

Testing Services™	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 4(4)
Author Data	Dates of Test	Report No	FCC ID	
Andrew Becker	March 1-2, 2012	RTS-5994-1203-63	L6AREY20CW	




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup

This report shall <u>NOT</u> be reproduced except in full without the written consent of RIM Testing Services Copyright 2005-2012 RIM Testing Services , A division of Research In Motion Limited