


IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos





IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos






IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos




This report shall NOT be reproduced except in full without the written consent of RIM Testing
ServicesA division of Research in Motion Limited.
Copyright 2005-2013Page 3 of 6



IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos




This report shall <u>NOT</u> be reproduced except in full without the written consent of RIM Testing Services A division of Research in Motion Limited. Copyright 2005-2013 Page 4 of 6



IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos






IC: 2503A-RFU80UW

Model: RFU81UW

Internal Photos



This report shall NOT be reproduced except in full without the written consent of RIM Testing
ServicesA division of Research in Motion Limited.
Copyright 2005-2013Page 6 of 6