

BlackBerry RTS	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW		1(4)
Author Data	Dates of Test	Report No	FCC ID
Daoud Attayi	Sep. 18-20, 2013	RTS-6050-1309-29	L6ARGF110LW

Annex E: Test set up photos

BlackBerry RTS	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW		Page 2(4)
	Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29
		FCC ID L6ARGF110LW	




Figure E1. BlackBerry Smartphone





Figure E2: Ambient noise and system validation measurement setup

BlackBerry RTS	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGF111LW		4(4)
Author Data Daoud Attayi	Dates of Test Sep. 18-20, 2013	Report No RTS-6050-1309-29	FCC ID L6ARGF110LW




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup