



**440 Phillip Street, Waterloo, Ontario, Canada**

Tel: (519) 888-7465 ; Fax: (519) 888-6906

Date: November 6, 2014

FCC OET Laboratory  
7435 Oakland Mills Rd.  
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: L6ARHH150LW

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: L6ARHH150LW to licensed services in 5.15-5.25 GHz occurs, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,

A handwritten signature in blue ink, reading "Masud S. Attayi".

---

Masud S. Attayi, P. Eng.

Manager, Regulatory Certification

EMC, Radio and RF Compliance

Email: [mattayi@blackberry.com](mailto:mattayi@blackberry.com)