



BABT  
Claremont House, 34 Molesey Road  
Walton on Thames  
Surrey, KT12 4RQ  
United Kingdom  
Telephone: +44 (0)1932 251200  
Fax: +44 (0)1932 251201

Ref: US/000025

15<sup>th</sup> October 2003

Direct Dial: +44 (0)1932 251247  
E-mail: [bill.wilson@babt.com](mailto:bill.wilson@babt.com)  
Website: [www.tuvps.co.uk](http://www.tuvps.co.uk)  
[www.babt.com](http://www.babt.com)

To FCC

**Evaluation of Class II Permissive Change to the Nokia Metrosite Edge Basestation  
(GSM800) Transceiver  
FCC id: L7KWTF A-01**

I have evaluated the submission and find it compliant.

During the evaluation the following clarification was made :

Report RG611553

Page 4, the calibration due date for test equipment item 1 was recorded as 21<sup>st</sup> January 2003 indicating that the item was out of calibration.

The test laboratory has clarified that this was a typographical error and should have read 21<sup>st</sup> January 2004. The test laboratory's letter is submitted with the test report in Exhibit 6

Yours sincerely

Bill Wilson

Technical Certifier