



Intertek Testing Services

ETL SEMKO

Report No.: 0209931
Talk Mode

Tested By: Hong, Report No.: 0209931

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 0209931
Talk Mode

Tested By: Hong, Report No.: 0209931

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement
Results:

no Results

Ctrl No.: N/A