

Cisco Systems, Inc. 125 West Tasman Drive San Jose, CA 95134-1706USA Phone: 408-526-4000 Fax: 408-526-4100 http://www.cisco.com

Differentially Statement

Date: Nov. 17. 2021

Deviation Statements

The Equipment Under Test (TTC7-30) uses Cisco module with type No 07-100577 (FCC ID: LDK073002357, IC: 2461N-073002357), with exact hardware version as certified.

The software deviations are: None.

EUT uses different external antennas than the ones in module certificates. Please refer to the antenna datasheet for details. The Cisco module 07-100577 is placed into a host configuration.

 Signature
 : Torbjørts Sudscalers

 Name and Job Title.
 : Torbjørn Sundsvalen, Hardware Engineer

 E-mail
 : tsundsva@cisco.com