




Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
Phone 408 526-4000  
Fax: 408 526 -4100  
<http://www.cisco.com>

Exhibit : Internal Photos

Model Number: CP-8821  
FCC ID: LDK88211296  
IC: 2461B-88211296

: Internal Views

LCD and Keypad are assembled first, then main PCB, ... so you could not remove LCD and Keypad first to show main PCB.




## Keypad and housing picture

Keypad top



Keypad bottom



This keypad connector  
to main PCB keypad  
connector




LCD Module:





LCD connection:



Top side of PCBA

