

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 Phone 408 526-4000 Fax: 408 526 -4100 http://www.cisco.com

Attestation Statements on compliance for CP-8861

The client device software does not support Active scanning on 2.4 GHz channels 12, 13, and 14. Further as the device does not have DFS detection capabilities, it only supports Passive scanning on the 5250- 5350 MHz and 5470- 5725MHz as required by FCC regulations and guidance. Accordingly passive scanning provides protection for TDWR operations and preventing transmission in the 5600MHz – 5650MHz frequency band.

Sincerely,

Those

Gerard Thorpe Manager Test Development Engineering