



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526 -4100
<http://www.cisco.com>

May 19, 2016

FCC ID: LDK88611057 CP-8861

This application is being submitted for the following reasons:

To move the DTS 5.8 band to UNII band under new requirements.
Update the other UNII bands to show they are compliant with new requirement.

In regards to U-NII bands 1, No power changes or software updates done. Device meets new rules

In regards to U-NII 2 band, this is a client only device , not effected by DFS changes, thus no additional testing was needed. Device meets new rules

In regards to U-NII 3 band, no power change occurred, Power operation is within Cisco tolerance for transmit power and thus no changes done. The issue is to demonstrate the device meets the new FCC OOB limits as specified, Data demonstrate device meets new rules.