

barcode label

compliance label



Product Name (产品名称 /Nom Du Produit): Video Phone (Video 电话)
 Model (型号/Modèle): CP-8875
 Manufacturer (制造商/Fabricant): Cisco Systems,Inc.

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Power input (輸入/Alimentation Entrée) 48V= 1.042A
 5.2/5.3 GHZ is limited to indoor use only in Japan
 US: XXXXXXXXX Cisco Systems, Inc.
 CAN ICES-003(B)/NMB-003(B) 170 West Tasman Drive San Jose, CA 95134, USA

2.4 DS/ OF 4



NYCE/CT/XXXX/XX/TS
 IFTEL: RCPICPXX/XXXX
 FCC ID: LDK88752517
 IC: 2461N-88752517



XXXX-XX-XXXX



MSIP-CMM-TNY-CP-XXXX



LR82435



<http://cisco-returns.com>

Made in China / 中国制造
 Fabriqué en Chine



Product Name (产品名称 /Nom Du Produit): Video Phone (Video 电话)
 Model (型号/Modèle): CP-8875
 Manufacturer (制造商/Fabricant): Cisco Systems,Inc.

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Power input (輸入/Alimentation Entrée) 48V= 1.042A
 5.2/5.3 GHZ is limited to indoor use only in Japan
 US: XXXXXXXXX Cisco Systems, Inc.
 CAN ICES-003(B)/NMB-003(B) 170 West Tasman Drive San Jose, CA 95134, USA

2.4 DS/ OF 4




NYCE/CT/XXXX/XX/TS
 IFTEL: RCPICPXX/XXXX
 FCC ID: LDK88752517
 IC: 2461N-88752517



XXXX-XX-XXXX



MSIP-CMM-TNY-CP-XXXX



LR82435



<http://cisco-returns.com>

Made in China / 中国制造
 Fabriqué en Chine

