



**Cisco Systems, Inc.**  
170 West Tasman Drive  
San Jose, CA 95134-1706  
Phone 408 526-4000  
Fax: 408 526 -4100  
<http://www.cisco.com>

May 19, 2016

FCC ID: LDKDX700976 CP-DX70

Submit a permissive Change to FCC Grant FCC ID: LDKDX700976

This Device was previously authorized under 15.247 to be modified to operate under the New Rules and technical requirements of 15.407 (b) (4) (i) with no changes in total power. This Device will be sold after 2020.