In response to RT 26874, the average power was inadvertently listed on the certificate based upon information on the bottom of page 38 of 59 (labeled 16 of 29 in the report). This has been corrected on the grant. Since RF exposure information in 2.1091 cites "In general, maximum average power levels must be used to determine compliance.", this change would not be expected to affect RF exposure which was originally calculated based upon maximum average power as allowed per 2.1091. Please let us know if there are any further concerns.

ATCB			
	-RT 2	6874 -	

To: William Graff From: Tim Harrington

Tim.Harrington@fcc.gov

FCC Equipment Authorization Branch

Re: FCC ID: LDKXSCLCR14

Applicant: Cisco Systems Inc

Correspondence Reference Number: 26874

731 Confirmation Number: TC371093 Date of Original Email: 03/02/2006

Subject: audit

TCB to address:

EMC report but not form731 appears to show P>20 dBm max power - please explain and/or revise

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal pursuant to Section 2.917(c).

DO NOT Reply to this email by using the Reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet at www.fcc.gov, E-Filing, OET TCB Electronic Filing, TCB Login. If the response is submitted through Add Attachments, a message which informs the processing staff that a new exhibit has been submitted must also be submitted via Submit Correspondence. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.			