

Continental Automotive Systems, Inc.

21440 West Lake Cook Road Deer Park, Illinois 60010, United States
TEL: 84786224354 FAX: 847-8628016

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2023-11-09

Reference: FCC ID: LHJ-STRLNK3P

To The Commission:

This Change of Identification request applies for a new FCC ID: LHJ-STRLNK3P as established in 47CFR 2.933(b) for a currently approved device. This application by **Continental Automotive Systems, Inc.** will establish a new FCC ID under LHJ grantee code for purpose of marketing. The original grant to **FCC ID: LHJ-STRLNK2P** will remain in effect.

An authorization letter by **Continental Automotive Systems, Inc.** is attached.
Per 2.933(b)

1. The original identification is **FCC ID: LHJ-STRLNK2P**
2. The original grant date is **03/05/2020**.
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

User manual

Sincerely yours,



James Zhang

Continental Automotive Systems, Inc.

TEL: 8478622435

FAX: 847-8628016

E-mail: Jianming.1.zhang@continental-corporation.com