



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 2, 2002

RE: FCC ID: LJPNC-1X
Attention: Kare Oksanen

I have a few comments on this Application.

- 1 The FCC requires separate test setup files and report files. Please separate the test setup photos and provide them as a separate file.
- 2 On the modulation limiting plots the vertical axis name has been blackened out. While it is obvious what this should be, please clarify the plots by labeling the vertical axis.
- 3 The voice bandwidth plot on page 21 of the report does not seem to have the typically expected characteristics of a 2500Hz modulated signal. Please explain.
- 4 Please provide an ESN attestation showing the device meets 22.919

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.