



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

April 4, 2002

RE: FCC ID: LJPKNW-1

I have a few comments on this SAR Application.

- 1 The reference dielectric and S/M values should be within 5%% of the measured values taken in the System Accuracy Verification. However, at 835MHz for the head verification done on 2/22/02 shows a reference value of 42.3 and a measured value of 39.5 for dielectric (ϵ_r). While this is within the +/-10% of the target value in IEEE std 1528, and explanation of the excessive percentage should be made. Please provide an explanation letter for this variance. You may upload this letter to the ATCB website for this application.
- 2 The Crest Factors used in the report do not have sufficient explanation as to their derivation or source. Please provide an example of the determination of the Crest Factor.

Dennis Ward
Dt Associates
PO Box 1644
Mariposa, CA 95338
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.