



(Photo 1)

FCC ID: LLA-TC300008




88122501

(Photo 2)




(Photo 3)

FCC ID: LLA-TC300008



(Photo 4)


FCC ID: LLA-TC300008



1

88122501

(Photo 5)




3

2


88122501

5


(Photo 6)



(Photo 7)




(Photo 8)




(Photo 9)


FCC ID: LLA-TC30008




(Photo 10)



(Photo 11)




(Photo 12)




88122501

(Photo 13)




88122501

(Photo 14)




88122501


(Photo 15)




(Photo 16)



(Photo 17)



(Photo 18)



(Photo 19)



(Photo 20)



(Photo 21)



(Photo 22)



(Photo 23)

FCC ID: LLA-TC30008