

ACLARA RF SYSTEMS
Former HEXAGRAM, Inc.
30400 Solon Road.
Solon, OH 44139
440-528-7200


September 8, 2011

Field Calibration and Tune-Up Procedure
FCC ID: LLB10005

Aclara RF's low power RF devices have passed through extensive testing and calibration procedures while in the factory. Therefore, no additional calibration, tuning, or adjustment is required in the field. Aclara RF's low power RF devices are shipped to the customer in the sealed enclosures. Thus, no adjustments or tuning can be made in the field, without breaking the factory sealed enclosure.

Sincerely,

Larry Murphy
Director of Engineering
Aclara
440-528-7559



Lmurphy@aclara.com